

## HDHU.14 Firmware Update

May 24<sup>th</sup>, 2022 ((Must have 032822 Installed))



1. Download the HDHU.14 Firmware Update and Save to Computer.

After downloading, make sure the compressed files are unzipped and are copied onto a blank USB Flash Drive (64GB Max) on the Root Directory File of USB Flash Drive

Format USB Drive in FAT32 Before Downloading Firmware

2. Insert USB stick and select the “Settings Icon” from the Home Screen



3. Select “System Settings” Tab at top, then next screen select “About” button



4. Select “Update” and on next screen select “Update” Again



**\*\* Wait for both Updates to complete**  
Headunit will restart itself once both updates are complete

New Firmware Info:

MCU – HDHU-14-220524

SOC – HDHU-14-220326 -18:00

Newest Firmware Improvements:

13-Band EQ, High-Pass Crossover  
Selectable Slope for F/R RCA's  
Subwoofer Crossover, 12dB Subsonic  
Additional Orange Touch Key Color

Need Help? Contact Tech-Support

[Tech-Support@PrecisionPower.com](mailto:Tech-Support@PrecisionPower.com) or 800-832-4647 Monday - Friday  
8:30AM – 4:30PM Pacific Standard

If Tech Support is busy, please leave a message and you will get a return call within 48 hours of being received. [For.Faster.Service.Email.Us](mailto:For.Faster.Service.Email.Us)